



VIA AIRBORNE EXPRESS

131 Morristown Road
Basking Ridge, NJ 07920

November 8, 1990

109957

Mr. William D. Steuteville
U.S. Environmental Protection Agency
841 Chestnut Building
Philadelphia, PA 19107

RE: Monthly Inspection
C & D Recycling Site
Foster Township, PA

Dear Bill:

Enclosed is the monthly inspection and maintenance report for the
C & D Recycling Site.

Sincerely,

A handwritten signature in cursive script that reads "Joe Chikowski".

Joe Chikowski
Senior Engineer

JTC/mhl

Enclosure

AR400984

B. E. S.

ENVIRONMENTAL SPECIALISTS INC.

And 24-Hour Emergency Response

P.O. BOX 1830

KINGSTON, PENNSYLVANIA 18704

Phone: (717) 779-5316

November 5, 1990

A T & T Corporation
131 Morristown Road Room B-2173
Basking Ridge, New Jersey 07920

Attention: Joseph T. Chikowski

Dear Mr. Chikowski;


Enclosed please find the completed copy of the site inspection report for the November site visit to the C & D Recycling site. All maintenance and corrective activities performed during this site inspection have been listed.

The October site survey was not done because we were waiting to set up a date when you could meet with my supervisor at C & D. I left messages on your machine to try to set one up.

Once again, thank you for your continued interest in the quality field services provided by B.E.S. Environmental Specialists, Inc.

Please feel free to contact our offices should you have any questions about this report or any additional site services.

Yours truly,



Lydia Hirner

enc.

C&D RECYCLING SITE
MONTHLY INSPECTION AND MAINTENANCE REPORT

SECTION I - GENERAL

1. Name of Company Performing Inspection:

B.E.S. Environmental Specialists, Inc.

2. Name of Inspector:

Brian Maher
Jeff Sequin

3. Beginning Date of this Inspection:

November 2, 1990

4. Site Map Reviewed:

YES

5. Previous Inspection and Maintenance Report Reviewed:

YES

6. Date of Previous Inspection:

September 13, 1990

7. Were any maintenance activities required on previous inspection report in which corrective action was not taken? NO If so, which activities were not completed.

AR400986

SECTION II - FIELD INSPECTION

(A site map must be taken to site.)

1. Site Security Fence: Walk Perimeter - Note Location of Deficiencies on Site Map.
 - o Warning Signs Intact? Yes X No If Not, Action Taken
 - o Chain Link Fence Intact? Yes No X If Not, Action Taken
Re-tied fencing
 - o Barbed Wire Intact? Yes X No If Not, Action Taken
 - o Gates Intact? Yes X No If Not, Action Taken
 - o Tension Wire Intact? Yes X No If Not, Action Taken
 - o Chain & Padlocks Intact? Yes X No If Not, Action Taken
 - o Additional Observations (Erosion under fence, loss of post support, etc.).

AR400987

2. Temporary Ash Cover: Inspect all three piles individually.

Northern Pile

- o Plastic Cover Intact? Yes ☐ No ☒ If Not, Action Taken
Replaced covering
- o Tire Hold-Down Intact? Yes ☒ No ☐ If Not, Action Taken
- o Perimeter Drainage Channel Intact? Yes ☒ No ☐ If Not, Action Taken
- o Additional Observations.

Central Pile

- o Plastic Cover Intact? Yes ☐ No ☒ If Not, Action Taken
Recovered half of it
- o Tire Hold-Down Intact? Yes ☒ No ☐ If Not, Action Taken

AR400988

o Perimeter Drainage Channel Intact? Yes X No If Not, Action Taken

o Additional Observations.

Southern Pile

o Plastic Cover Intact? Yes No X If Not, Action Taken

Re-covered with poly

o Tire Hold-Down Intact? Yes No X If Not, Action Taken

Used sand-bags and rocks to re-inforce it.

o Perimeter Drainage Channel Intact? Yes X No If Not, Action Taken

o Additional Observations.

3. Drainage Channel: Walk entire length - Note location of deficiencies on Site Map.

o Riprap Layer Intact? Yes No X If Not, Action Taken

Rip-rap is still needed

AR400989

- o Geotextile Intact? Yes X No If Not, Action Taken
- o Subgrade providing adequate support to bottom and sideslopes? Yes X
No If Not, Action Taken
- o Channel Unobstructed? Yes X No If Not, Action Taken
- o Additional Observations.

4. Silt Fence: Walk all reaches - note location of deficiencies on Site Map.

- o Silt Fence Intact? Yes X No If Not, Action Taken
- o Fabric Secured to Posts? Yes X No If Not, Action Taken
- o Fabric Entrenched Into Soil? Yes No X If Not, Action Taken
Re-buried the fence in several locations
- o Runoff Flowing Through Fence and Not Around Fence. Yes X No If
Not, Action Taken
- o Additional Observations.

AR400990

5. CMP Drainage Pipe Downdrain: Walk entire length - note location of deficiencies on Site Map.

- o Pipe Connections Intact? Yes X No ____ If Not, Action Taken
- o Anchor Bars Embedded and Intact? Yes X No ____ If Not, Action Taken
- o Outlet Area Intact? Yes X No ____ If Not, Action Taken
- o Pipe Outlet Unobstructed? Yes X No ____ If Not, Action Taken
- o Additional Observations.

AR400991

PAGE -7-

SECTION III - SUMMARY

Date Inspection and Maintenance Activities were completed:

List of maintenance activities which were not completed at the time that this report was prepared:

Brian Traker 11-2-90

SIGNATURE OF INSPECTOR/DATE

AR400992

